

# SENTRY FLOOR SAFETY TREATMENT

## Slippery Shiny Sealed Surfaces?

Sentry Floor Safety Treatment is a one step process to clean floors and increase slip resistance (wet surfaces) and coefficient of friction (dry surfaces). The Sentry one step process is more practical and economical (labor and product) than multiple floor products.

***Dries to a shiny surface or can be buffed to a high shine***

### **USE ON:**

**'Wet look' high gloss** – vinyl, linoleum

**Polished** – marble, granite

**Sealed** – marble, terrazzo, Chattahoochee stone

**Waxed** – wood, vinyl, linoleum, marble, stone

**Acrylic** – wood

**Epoxy** - test for suitability before general use.

### **FEATURES**

Economical – one product, one step, lower labor costs

Reduce slip & falls: slip resistant on wet and dry floors

Water base, non toxic, non flammable

Daily 1 step mop & bucket - clean & increase grip on surface

Dries to shine & can also be buffed

### **PACKAGING**

Available in: 1 gallon containers

5 gallon pails

55 gallon drums

### **Application Directions**

Sweep, mop or dust to remove loose debris prior to application

Allied Member AH&LA and NRA

Phone: (416) 256 4335

E-mail: [info@slipandfallsolutions.com](mailto:info@slipandfallsolutions.com)

# SENTRY FLOOR SAFETY TREATMENT

**Daily Cleaning/Safety Treatment:** Mix 2 oz. of Sentry per gallon of cold water and apply with a mop. Rinsing is not required, but if selected, adjust concentration to 4 oz. per gallon.

**Heavily Soiled Floors/Safety Treatment:** Mix 4 oz. Sentry per gallon of cold water. Scrubbing recommended. If necessary mop twice with Sentry mixture.

**Initial High Gloss Restoration/Safety Treatment:** Mix 8 oz. of Sentry per gallon of cold water. On a clean floor mop an even, wet coat of the mixture and let dry. Buff the entire area.

**Waxed Surfaces/Safety Treatment:** See 'Daily Cleaning' or 'Initial High Gloss Restoration'. Buff the entire area if high shine desired

**Spray Buffing/Safety Treatment:** Mix 1 part Sentry to 10 parts cold water and apply with a trigger sprayer. Use high speed or standard speed equipment.

**Automatic Scrubbers**    *Use red or white scrub pads*

**Initial Cleaning/Slip Treatment:** mix 8 oz. Sentry per gallon of cold water.

**Daily Cleaning:** mix 2 oz. Sentry per gallon of cold water.

**Heavily Soiled Floor:** mix 4 oz. Sentry per gallon of cold water.

**Clean up:** Clean application tools, machinery and spills with clean water.

**For Optimum Results**    Use Sentry as a daily cleaning/safety program  
**DO NOT** mix with other chemicals  
Water rinse is not required  
Use cold water to extend longevity of finish

## **Technical Data**

Diluents: Water

Cleanup: Water

Toxicity: None

Fumes: None

Flammability: None

Freeze Harm: None

Freeze Temperature: 32 degrees F

Allied Member AH&LA and NRA

Phone: (416) 256 4335    E-mail: [info@slipandfallsolutions.com](mailto:info@slipandfallsolutions.com)